

---

PuMA measure

## RR31 AMP fails coding with ISTA 4.25.x

UR-V-2 65494848-01 - 9/24/20

### Complaint:

During a programming session with ISTA 4.25.x, the AMP fails coding

---

### Cause

Incorrect coding data

---

### Measure

If the Amp is listed as failing coding after a programming session, please raise TSARA case for further support. Rolls-Royce technical support will be able to code the AMP via IRAP. Please have the vehicle ready for an IRAP session before raising the case.

The issue will be resolved with ISTA version 4.25.3x due to be released at the end of September 2020.

\*\*\*Note\*\*\*

The vehicle should not be released to the customer until Rolls-Royce Technical support have

---

### Validity information

Model series:	[RR31]
Engine range:	[ALL]
Body style:	[ALL]
Fault codes:	[]
Production period:	-

---

### Repair overviews

65/12/002/12658/38088, Audio amplifier, code, Cannot be encoded with VFC, , Encoding not possible, , Program/Coding