

## GPOP - Issue Review System

**Part Number:** 68443470A\$

**Part Description:** SENSOR, Tire Pressure

**Issue Description:** For concern of TPM warning lamp on or missing signal related DTCs, please ensure correct TPMS diagnosis and repair. In order to determine proper root cause, please note if sensors are broken and email pictures of sensor before removal to *FCA Redacted Content*.

Analysis of TPM Sensor warranty returns are reported back as TNF or TPM Sensors are returned damaged( cracked or broken) and cannot be analyzed to determine failure mode.

~ \_\_\_\_\_ ~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---

