

GPOP - Issue Review System

Part Number: 04627371A\$, 04627633A\$, 06510314A\$

Part Description: Intake Manifold, Intake Manifold Gaskets, Intake Manifold Bolts

Issue Description: If the intake manifold is being removed for service and the vehicle build date is between 02/24/20 to 08/07/20, please inspect the intake manifold for cracks around the intake manifold mounting bolt holes. If cracks are found please replace the intake manifold and intake manifold mounting bolts with P/N 06510314AA or later, torqueing the bolts to specification when installing. If no cracks are found around the mounting holes, the intake manifold is OK to re-install during re-assembly using NEW mounting bolts P/N 06510314AA or later and torqueing to specification.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
~

