

GPOP - Issue Review System

Part Number: 68445818A\$

Part Description: WIRING, Front Fascia

Issue Description: For DTC codes U11E9 and/or P0073 and you confirm corrosion or water at the XY101 Connector:

1. Order connector repair kits as appropriate (meaning no corrosion at other connectors) repair connectors using the following kits:
68500834AA Fascia side (Available by Q4 2020)
68497543AA Dash Side
(If excessive corrosion is found, the entire harness may need replacement)

2. Please contact *FCA Redacted Content* to return BOTH the female and male side of the XY101 together.

If no response in 15 minutes, proceed with repair.

~ _____ ~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

