

## GPOP - Issue Review System

**Part Number:** L0007444N\$

**Part Description:** BULB, Park and Turn Signal

**Issue Description:** For concern of turn signal bulb inoperative/broken or blown, please replace the entire lamp assembly (55112720A\$ or 55112721A\$) instead of replacing the affected turn signal bulb.

Please call *FCA Redacted Content* prior to replacing the component (if needed).

If no response in 15 minutes, proceed with repair.

~ \_\_\_\_\_ ~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

