

GPOP - Issue Review System

Part Number: 68089578A\$

Part Description: Power Distribution Center, Intelligent Power (TIPM)

Issue Description: Certain levels of this part were changed to remove additional content not needed on light duty truck. Content removed was only used on heavy duty truck and not needed for light duty vehicles.

Content that may not be present includes the following fuses:

F15 (J Case A1-S)

F16 (M Case)

F32 (M Case)

F33 (M Case)

F34 (M Case)

F39 (M Case)

If the PDC is being replaced due to a failed internal fuel pump relay, the relay can now be serviced as a separate component. Please use relay replacement KIT part number: 68510768A\$.

~ _____ ~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
