







STAR ONLINE PUBLICATION

Case Number: S2008000144

Release Date: 9/29/2020

Symptom/Vehicle Issue: External Fuel Pump Relay Kit Now Available

Discussion: Engineering has developed a kit to service the Fuel Pump Relay which is internal to the PDC. This will eliminate the need for the PDC to be replaced due to a fuel pump relay failure as the relay can now be serviced as a separate component.

Please use relay replacement Kit Part Number: 68510768AA.

The installation instructions will be provided with the Kit.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found