Subject: Engineering Information – Loud Bang and/or Grinding Type Noise Heard Coming From the Rear Axle

This PI has been revised to end the need for information from the field. Please discard PIE0558.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2015	2020	-	-	Equipped with 2.5L, 3.6L, 2.8L	Equipped with 6SPD, 8SPD Transmissions
GMC	Canyon					Engines (RPOs LCV, LGZ, LWN, LFX)	(RPOs MYB, M5T)

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2	
Modified	Released March 23, 2020 Revised September 02, 2020 – Ended the need for further information from the field.	