

Oil Filler Plug, Hub Cap Side, Adjustment VN, VHD


FSB 773-004 Oil Filler Plug, Hub Cap Side, Adjustment

(October 2020)

On certain Volvo trucks, models VN and VHD built from June 29th, 2020 through July 24th 2020 and equipped with SKF hubcap part number 23873065, a loose fill plug has been reported in some cases.


If this condition is found, follow instructions outlined in FSB.

- 1 Park the vehicle on a flat and level surface.
- 2 Apply the parking brake. .
- 3 Install the wheel chocks.




W7086748

- 4 Check oil level in the hub.
Note: Ensure oil level is correct.
- 5 Tighten the fill plug to 25 in.lbf (Finger tight).



T7164480

6 Remove the wheel chocks.



W7086759

Reimbursement

This repair may be eligible for reimbursement if a product failure was experienced within time and mileage limits of the applicable Warranty coverage. Reimbursement is obtained via the normal claim handling process.	UCHP Reimbursement
Claim Type (used only when uploading from the Dealer Bus. Sys.)	01
Labor Code	
Primary Labor Code	7731-05-09-01 0.1 hr
Causal Part	23873065

VOLVO Trucks North America reserves the right to make any changes in design or to make additions to or upon its products without incurring any obligations to install the same on vehicles previously built.