

p4 gcw04t flashed to 19.45.1



[Vincent Boyce](#) 10 posts since Nov 20, 2014

p4 gcw04t flashed to 19.45.1 Oct 15, 2020 5:35 PM

I have a 2020 P4 Vin MK6987 that came in with the common gate way flashed to Software 19.41.1 from 19.38.0 forward camera and lane camera not communicating not finding VRDU. It made a hardware change is there any way to bring this Back to its original set up with out replacing the CGW. and if I have to replace it does the server have the new hardware and software listed are will it let me load to original 19.38.0 when It changes the VIN



[Jon Cecil](#) 848 posts since Nov 25, 2014

Re: p4 gcw04t flashed to 19.45.1 Oct 15, 2020 7:07 PM

You can try reprogramming to OEM through program device