

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922



| | |
|--|-------------------------------------|
| Subject: LOCTITE 962T NO LONGER AVAILABLE FOR SKYACTIV CYLINDER HEAD INSTALLATION | Service Alert No.: SA-071/20 |
| | Last Issued: 10/28/2020 |

APPLICABLE MODEL(S)/VINS

| | | |
|-----------------------------|----------------|-----------------|
| 2012-2013 Mazda3 (SKYACTIV) | 2013-2021 CX-5 | 2016-2021 MX-5 |
| 2014-2021 Mazda3 | 2016-2021 CX-3 | 2020-2021 CX-30 |
| 2014-2021 Mazda6 | 2016-2021 CX-9 | |

DESCRIPTION

Currently, the instructions on MGSS recommend the use of Loctite 962T or equivalent when installing a SKYACTIV cylinder head, but it is no longer available. The following 3 adhesives are alternatives available as an equivalent to Loctite 962T:

- Loctite 272
- Loctite 518
- Threebond TB-1386H

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.