

LTB00761NAS2



TECHNICAL BULLETIN

05 OCT 2020

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

This bulletin supersedes TSB LTB00761NAS1/2015 dated 19 MAY 2015, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). Only refer to the electronic version of this Technical Bulletin in TOPIx.

Changes are highlighted in blue

SECTION:

501-08

SUBJECT/CONCERN:

Hood Finisher Paint / Lacquer Flaking

AFFECTED VEHICLE RANGE:

MODEL:

MODEL YEAR:

VIN:

ASSEMBLY PLANT:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Range Rover (LG)	2013-2016	000001-244690	Solihull

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

The hood finisher may show signs of the paint and/or lacquer 'flaking'.

CAUSE:

This may be caused by poor paint adherence between the base coat and clear lacquer.

ACTION:

Follow the instructions below.

PARTS:

PART NUMBER	DESCRIPTION	QUANTITY
LR077005	Hood finisher - Dark Atlas	1

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.
- The JLR claims submission system requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
-------------	-----	--------------	----------------	-------------

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Hood finisher - Renew	76.43.27	0.1	D4	LR064762

NOTE:


Normal Warranty procedures apply.

SERVICE INSTRUCTION:

1.

CAUTION:

make sure no damage is caused to the paintwork.




Use a suitable tool to remove the hood finisher.

2.

CAUTION:

make sure no damage is caused to the paintwork.



Install the new hood finisher.