

**Complaints - Apple iPhone® Cannot Be Connected Via USB Cable. (SY 133/19)**

Vehicle Type: **Cayenne (9YA)/Macan (95B)**

Model Year: **As of 2019**

Subject: **PCM 5.x**

Information: **Apple iPhone cannot be connected via USB cable**

Remedial Action: Connect the Apple iPhone to the PCM via WiFi first. After you have done this once, the iPhone can be connected via USB cable in the future.

**Invoicing**

Invoicing: For documentation and warranty invoicing, enter the POIS coding specified below in the warranty claim:

<b>Location (FES5)</b>	91520	Central computer
<b>Damage type (SA4)</b>	1612	Does not function in some cases

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.