

# WLL6 Stop Delivery - Rework adjustment screws on the rear axle

Version 2

---

## Update 10/27

Please find the attached remedy rework instructions to complete the WLL6 campaign.  
The affected vehicle can now be reworked and unblocked according to these instructions.

---

## Important Reminder

**IT IS A VIOLATION OF FEDERAL LAW FOR DEALERS TO DELIVER TO CUSTOMERS NEW VEHICLES IN THEIR INVENTORY AFFECTED BY THIS NOTIFICATION UNTIL THESE VEHICLES ARE REMEDIED. DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.**

English (US)

- > Vehicle blocking
- > Overview
- > Vehicle usage
- > Test instructions and remedial measures
- > Subsequent procedure

## WLL6 Stop Delivery - Rework adjustment screws on the rear axle

### Vehicle blocking

Vehicles must not be delivered to customers until the required remedial measure has been carried out. Therefore, please carry out following Stop Delivery, immediately.

### Overview

On the affected vehicles, there is the possibility that the eccentric screws on the rear axle for adjusting toe and camber have not been tightened to the prescribed torque.

This can lead to noises from the rear axle area when driving in curves.

For this reason, toe and camber on the rear axle must be re-adjusted and the eccentric screws must be tightened to the prescribed torque before delivery of the the respective vehicle.

Model type	Taycan 4S (Y1A)
Model year	2020
Number of affected vehicles	1
Affected VIN	WPOAB2Y10LSA54045
Last contact at dealer number	4500581

### Vehicle usage

The vehicles may only be driven for loading and unloading purposes in the transport chain.

Further use is not permitted. Test drives are to be omitted.

## Test instructions and remedial measures

See Attached

## Subsequent procedure

Please inform the necessary dealer employees in the Sales, Management and Aftersales departments.

[WLL6\\_Rework\\_instructions.pdf](#)

**546.2 KB**

(56 views)

[WLL6 Stop Delivery VIN List.xlsx](#)

**8.0 KB**

(115 views)

Created by [Ryan Cooney](#) on Oct 26, 2020 6:18 PM. Last modified by [Ryan Cooney](#) on Oct 27, 2020 1:26 PM.

Categories: Taycan, Workshop Campaigns, Stop Sale

Tags : [stop delivery](#), [taycan](#), [year\\_l](#), [wll6](#)

977 Views

[Report Abuse](#)

### Content and Topics

Your Groups >

Your Content >

Your Places >

### Personal

Edit Profile >

Change Password >

### Manage

Admin Console >

PPN Administration >

### Create

Discussion >

Files >

Document >

Collaboration >

Document

Blog Post >

Poll >

Event >

Photo Album >

Idea >

Space >

Group >

© 2020 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. [009](#)