



GROUP STEERING	NUMBER 20-ST-004HG
DATE OCTOBER, 2020	MODEL(S) G80 (DH)

Technical Service Bulletin

SUBJECT: 18MY GENESIS G80 (DH) STEERING GEAR ASSEMBLY

Description: This bulletin provides repair information on certain 18MY G80 (DH) vehicles equipped with a 4-bolt steering gear assembly. If a vehicle exhibits a center biased steering feel, and no DTC(s) are active in the steering system, it is recommended to replace the rack-mounted motor driven power steering (R-MDPS) assembly using the updated part numbers shown below.



Applicable Vehicles:

18MY Genesis G80 (DH) 3.8L AWD, 5.0L AWD, and 3.3T RWD & AWD vehicles produced through September 5, 2017.

Parts Information:

Part Name	Previous Part Number	New Part Number	Remarks
R-MDPS Assembly	57700-B1300	57700-B1301	3.8L V6 AWD, 3.3T RWD & AWD
	57700-B1350	57700-B1351	5.0L V8 AWD

SUBJECT:

G80 (DH) STEERING GEAR ASSEMBLY

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
G80 (DH)	56500R00	GEAR BOX ASSY-STEERING	Refer to WEBLTS for current LTS time	57700-B1300 (3.8L AWD, 3.3T RWD/AWD)	H15	ZZ1
				57700-B1350 (5.0L AWD)		

Note:

Normal warranty applies.

Service Procedure:

Refer to the applicable model shop manual for detailed repair service procedures.

NOTICE

- Replace the lower steering shaft universal joint bolt with a new one.
- Check and adjust (if necessary) the vehicle wheel alignment after replacing steering gear box MDPS assembly.