

CAMPAIGN LAUNCH STATUS

SERVICE ACTIONS – VVT SOLENOID - AJ20P 4 CYL ENGINE



CSP SERVICE ACTION N481

AFFECTED MODELS	2018-2020 MY DISCOVERY SPORT; EVOQUE; DISCOVERY, RR VELAR; RANGE ROVER; RANGE ROVER SPORT. 4cyl AJ20P engines
VEHICLE VOLUME AFFECTED	53,094 USA 5,226 CAN
REPAIR	To prevent premature wear, a resulting MIL and a possible no start, all affected vehicles require the replacement of variable valve timing (VVT) solenoids on both intake an exhaust.
REPAIR TIME	Between 0.3 and 0.8 hrs based on model + drive in/out
CAMPAIGN LAUNCH	Phase 1 Oct 14 th 2020
Notes	Launch is staggered in VIN batches over a 3 month period Phase 1 10,700 VIN includes 90 unsold units..

CSP SERVICE ACTION H299

AFFECTED MODELS	2018-2020MY F-TYPE; F-PACE; XE; XF; E-PACE 4cyl AJ20P engines
VEHICLE VOLUME AFFECTED	37,827 USA 4,037 CAN
REPAIR	To prevent premature wear, a resulting MIL and a possible no start, all affected vehicles require the replacement of variable valve timing (VVT) solenoids on both intake an exhaust.
REPAIR TIME	Between 0.2 and 0.6 hrs based on model + Drive in/out
CAMPAIGN LAUNCH	Phase 1 Oct 14 th 2020
Notes	Launch is staggered in VIN batches over a 3 month period Phase 1 c 14,500 VIN includes 200 unsold units.