

## TECHNICAL TOPICS POWERTRAIN



### Belt Breaking with no FEAD Damage

20MY – Onward Range Rover, RR Sport, Defender equipped with AJ20P6

#### Customer Voice:

- The Charge Warning message is on.
- The Check Engine Lamp is illuminated.

#### Technical Description:

- The FEAD belt is found broken.
- The FEAD pulleys are properly aligned and confirmed to spin freely.

#### Status:

- This topic is currently under investigation.
- Perform a thorough inspection of all the pulleys and mounting hardware in the FEAD system.
- Have the service advisor confirm with the customer if any noises were heard prior to the service visit.
- Retain the original belt for return and create an EPQR.

