

## TECHNICAL TOPICS

### BODY/CHASSIS



#### Knocking Noise From Front Suspension Lower Control Arms

20MY RR Evoque & Discovery Sport

##### Customer Voice:

- A customer may report a knocking type noise from the front suspension while driving.

##### Technical Description:

- The fluid in the lower control arm hydrabush is moving around within the bushing creating a fluid knock noise.

##### Status:

- TSB LTB01294NAS3 was published to address this concern, but the supplier production could not meet the demand of parts, this TSB has now been removed.
- A revised repair procedure has been developed by engineering that eliminates the need to replace parts for this concern.
- TSB JLRTB02060 has just been published to provide a process to drain the hydrabushes currently on the vehicle.

