TECHNICAL TOPICS BODY/CHASSIS





Air Conditioning Blowing Warm Air	20MY Range Rover Evoque
 <u>Customer Voice</u>: A customer may report that the HVAC system is not blowing cool air. <u>Technical Description</u>: The air conditioning system may be low on refrigerant due to a slow refrigerant leak within the system. <u>Status</u>: Engineering is investigating reports of refrigerant leaks in the system. Should a customer report a concern of lack of cooling and the cause is determined to be due to a refrigerant leak, please submit an EPQR with pictures of point of the leak in the system. 	HN2 1A194C HN2 1A194C HR3 HA194B HR3 HR1 JBB67 HR3 HR1 JBB67 HR3 HR1 JBB67 HR1 JBB67 HR3 HR1 JBB67 HR1 JB6
Image: Second state Image: Second state Imag	43