

# Special Service Message

NOTE: A Special Service Message is a formal communication issued by Jaguar and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Jaguar technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

**SSM 75114 - F-Pace SVR MY18 Onwards Investigation of Exhaust Tailpipe / Actuator Rattle**

**Models :** F-Pace / X761

**Engineer** Skingle Paul

**Name :**

**Last Modified** 19 OCT 2020 11:44:43

:

**Category :** Noise Vibration

**Symptom :** 702000 Other Noise Concerns

**Content :** Issue:

JLR is investigating an issue of exhaust tailpipe actuator rattle noise on F-Pace SVR models.

Cause:

Unknown at this time.

Action:

Before replacing any hardware component's in an attempt to resolve the issue.

1. Please send a video of the rattle / noise concerns to [jettel@jaguarlandrover.com](mailto:jettel@jaguarlandrover.com) for further correspondence