

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 74828 - Range Rover Sport SVR MY18 Onwards Investigation of Exhaust Tailpipe / Actuator Rattle.

Models : Range Rover Sport / L494

Engineer Skingle Paul

Name :

Last Modified 20 OCT 2020 20:56:23

:

Category : Noise Vibration

Symptom : 702000 Other Noise Concerns

Content : Issue:

JLR is investigating an issue of exhaust tailpipe actuator rattle noise on Range Rover Sport SVR models.

Cause:

Unknown at this time.

Action:

Before replacing any hardware componets in an attempt to resolve the issue.

1. Please send a video of the rattle / noise concens to jettel@jaguarlandrover.com for further correspondence.