VOLVO CAR SERVICE AND PARTS BUSINESS



Technical Journal

TITLE: Loose trim moulding rear door

REF NO:	ISSUING DEPARTMENT:	CAR MARKET:		
TJ 35197.1.2	Technical Service	United States and Canada		
	PARTNER:	ISSUE DATE:	STATUS DATE:	
3 US 7	510 Volvo Car USA	2020-10-19	2020-10-22	
FUNC GROUP:	FUNC DESC:			
8414	Trim moulding at window	Page 1 of 6		

"Right first time in Time"

Attachment

File Name	File Size
TJI-405787_2_1_1.pdf	0.3279 MB

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If vehicle shows symptom for loose trim moulding on rear door window, follow advice under service.

CSC Customer Symptom Codes

Code	Description
M3	Exterior trim/components/Moldings, trim loose
M4	Exterior trim/components/Moldings, trim poorly aligned or fit

DTC Diagnostic Trouble Codes

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-2020		0000001-0066296	201835-202012

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste. © 2020 VOLVO CAR USA, LLC

Technical Journal 35197.1.2



SERVICE:

Perform the repair according to attached method.

Use WURTH tape PN 894910 (Canada) Use WURTH tape PN 189412 (US)

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data: VST OP number: 99922-2 Refer to CPI 16-2019 for claiming WURTH part numbers.

VST OP number: 99922-2 Refer to CPI 16-2019 for claiming WURTH part numbers.

VST Operation Number

VST Operation Number	Description
99922-2	General reimbursement acc. to TJ/QB

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8414.

To view TJ attachment continue to next page. This TJ has one attachment.

Volvo	Car Customer Service	TJ Instruction VCC-405787-2		
Title	Weatherstrip, door window, rear	Page	1 (4)	
Action	Product fix	Operation number:	99922-2	
L		· · · · · · · · · · · · · · · · · · ·		


Issue	Date	Reason
1	2020-03	First issue

Affected vehicles

Model year	
2019, 2020	S60 (19-)

Materials					
Materials	Qty.	Part No.	Notes		
Таре	0.01	894910			


Removal




845 - sealing and protect. molding for

door, lid, and side window


Adjustment





TJ Instruction VCC-405787-2

Page 4 (4)



Installation

To install, reverse the removal procedure.