



Preliminary Information

PIC6408A Diagnostic Tip - Service Driver Assist - Image Processing Module U0512

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT5	2020	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UGN
Condition	Service Driver Assist message with Image Processing Module setting U0512
Cause	Software

Correction:

At this time clear the DTC and verify it does not return. If the DTC immediately returns, follow normal SI Diagnostics.

Engineering is working on a software update to address this concern.

This PI will be converted to a bulletin when a permanent solution is available.

Version History

Version	2
Modified	03/18/2020 - Created on 04/08/2020 - Updated title and keywords..

