
PuMA measure

RR31 - Change of Torque - Sunroof fixings

UR-V-2 65501910-01 - 10/26/20

Complaint:

Noise detected from the sun roof area whilst driving over undulating or rough roads.

Cause

Fixing torque of bolts securing sunroof frame to the body have been increased.

Measure

With immediate effect the sunroof fixing torque has been changed from 5.4Nm to 6.5Nm.
ISTA/AIR will be updated shortly.

When completing repairs to the sunroof the new fixing torque of 6.5Nm must be used.

ISTA REP 54 13 080 Removing and Installing/replacing slide/tilt sunroof fully

Validity information

Model series:	[RR31]
Engine range:	[ALL]
Body style:	[ALL]
Fault codes:	[]
Production period:	-

Repair overviews

54/10/001/27846, Panorama glass roof / sliding / tilting sunroof, complete, Area, roofliner, centre, , Torque fault, , Checking, repairing, replacing

Attachments

Number of attachments: 1