
PuMA measure

RR2x - Bonnet touches scuttle trim when opening

UR-V-2 65502971-01 - 10/29/20

Complaint:

A short 'click' noise may be audible when opening the bonnet, from either hinge area.

Cause

Due to the mechanical action of the hinge, it can contact the top edge of the scuttle panel trim at the base of the windscreen.

The scuttle panel trim seal, by design, must remain at this height in order to provide effective water management in this area of the vehicle.

Attached to this measure is a short video to demonstrate the situation.

Measure

No action required. The scuttle trim must not be trimmed as it is critical for water management in this area of the vehicle.

No long term effects of the touch condition have been found during development and validation processes of the vehicle launch.

Validity information

Model series:	[RR22, RR21]
Engine range:	[ALL]
Body style:	[ALL]
Fault codes:	[]
Production period:	-

Repair overviews

41/00/010/12104, Bonnet hinge, complete, Both sides / all, , Ticktack noise / cracking noise (disturbing noise), , No action

Attachments

Number of attachments: 1