



STAR ONLINE PUBLICATION

Case Number: S2010000001

Release Date: 10/07/2020


Symptom/Vehicle Issue: Customer complaint of air bag lamp on. B0029-11-RIGHT CURTAIN DEPLOYMENT SQUIB 1-CIRCUIT SHORT TO GROUND

Discussion: Customer states the air bag light is on and DTC B0029-11 is retrieved from the ORC module. Remove the c-pillar trim and inspect the wiring around the pillar attachment points. Repair as needed. Follow service information for wire splice repairs-10 - Restraints / Standard Procedure SUPPLEMENTAL RESTRAINT SYSTEM WIRING REPAIRS

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

STAR ONLINE PUBLICATION



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found