

STAR ONLINE PUBLICATION

Case Number: S2008000163

Release Date: 10/24/2020

Symptom/Vehicle Issue: CEL (Check Engine Light) Came On After Start-Up

Customer Complaint/ Technician Observation: Owners complains that the check engine lamp came on after starting the vehicle. Technician observed the vehicle had been in for recent repair service and or was a low mileage vehicle, DTC P0440 Evaporative Emission System and/or P0456 EVAP Small Leak Detection as stored as active.

Discussion: Inspect the location of the ESIM connector D2812A at the ESIM to ensure all component connectors are fastened securely Fig 1, 2.




Fig 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

STAR ONLINE PUBLICATION



Fig 2

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found