



Service Bulletin


Bulletin No.: 16-NA-059

Date: October, 2020

INFORMATION

Subject: Staining/Discoloring to Brake Caliper Paint


Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	ATS-V	2016	2018	—		All	All
	CTS-V	2016	2018				
Chevrolet	Camaro	2012	2021				
	Corvette	2014	2020				

Involved Region or Country	North America, Europe, Russia, Middle East, Israel, Argentina, Brazil, Bolivia, Chile, Colombia, Ecuador, Paraguay, Peru, Uruguay, Japan, GM Korea Company, China, Taiwan, Philippines
Condition	 <p style="text-align: right; font-size: small;">4422999</p> <p>Some customers may comment on a discoloration or black stain on the paint of the brake calipers.</p>
Cause	This may be caused by high brake pad temperatures during aggressive driving or track event tarnishing the caliper paint.

Correction

Important: Do NOT replace the brake calipers for this condition.

This is not a defect in the paint or the caliper.



4423001

Legend

- (1) Not cleaned using mild polishing compound
- (2) Cleaned using mild polishing compound

If the customer wishes to have the black stain removed, a very mild polishing compound can be used to remove the stain.

Important: Do NOT use harsh chemicals or brake cleaner to attempt to remove the stain. This could damage the paint on the caliper.

Warranty Information

Labor fees associated with cleaning the calipers should NOT be charged under warranty. Rather, this should be customer pay.

Version	3
Modified	May 30, 2017 – Updated the Models and Model Years. October 14, 2020 – Updated the Models, Model Years and updated formatting to remove Attention statement and add the Involved Region or Country section.

