

## **Service Bulletin**

Bulletin No.: 17-NA-261

Date: October, 2020

## **INFORMATION**

Subject: Engine Overheat When Driving Aggressively with Accessory Grille and Outboard Cooler Installed

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to	Eligille.	mansinission.
Chevrolet	Camaro	2016	2021	_		All	All

Involved Region or Country	North America, Europe, Russia, Middle East, Israel, Palestine, Argentina, Brazil, Chile, Colombia, Ecuador, Paraguay, Peru, Uruguay, Japan, Cadillac Korea (South Korea), GM Korea Company, China, Taiwan, Thailand, Singapore, Philippines, Africa
Additional Options (RPOs)	Equipped with Accessory Grille (RPO RZ9 or RZB) and Aux Engine Cooler (RPO V18)
Condition	Some customers may comment on the engine overheating when driving aggressively with accessory grille installed in addition to an outboard cooler installed.
Cause	This may be due to outboard aero blockers restricting airflow to the outboard coolers, causing the engine to overheat.
Correction	If the vehicle is equipped with (RPO V18) outboard coolers and an accessory grille, the grille blockers should not be installed. If installed, they should be removed.

Version	3
Modified	October 16, 2017 – Added the 2017 and 2018 Model Years.  October 02, 2020 – Added the 2019-2021 Model Years and updated the Involved Region or Country section.

