

Service Bulletin

TECHNICAL

Brand:	Model:	Model Year:		VIN:		Engine	Transmission:
		from	to	from	to	Engine:	Transmission.
Chevrolet	Camaro	2016	2021	_		6.2L (LT1, LT4)	—

Involved Region or Country	North America, Europe, Russia, Middle East, Israel, Argentina, Brazil, Bolivia, Chile, Colombia, Ecuador, Paraguay, Peru, Uruguay, Japan, GM Korea Company, China, Taiwan, Philippines	
Condition Some customers may comment that a flutter type noise is emitting from the vehicle or from the console/shifter area.		
Cause	This condition may be caused by a damaged propeller shaft center support bearing.	
Correction	If the center bearing has been found to be the cause of the noise, replace the center support bearing.	

Service Procedure

Refer to Propeller Shaft Center Support Bearing Replacement in SI.

Parts Information

Causal Part	Engine	Description	Part Number	Qty
х	LT1 (2016- 2019)	BEARING, PROP SHF CTR SUPT	84515638	1
х	LT4 (2017- 2019)	BEARING, PROP SHF CTR SUPT	84470372	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
3020010	Propeller Shaft Center Support Bearing Replacement	Use Published Labor Operation Time

Version	2
Modified	Released November 19, 2019 October 09, 2020 – Added the 2020-2021 Model Years and updated the Involved Region or Country section.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION