



# Service Bulletin

Bulletin No.: 20-NA-214

Date: November, 2020

## INFORMATION

**Subject:** Information on Front Side Door Window Intermittently Auto Reverses When Going Up or Down

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2020	2020	—	—	All	All

<b>Involved Region or Country</b>	North America, Saudi Arabia
<b>Condition</b>	Some customers may comment that when they are operating either door glass up or down, the window may intermittently auto reverse.
<b>Cause</b>	The cause of the condition may be that the door window may be out of adjustment.
<b>Correction</b>	<b>Note:</b> DO NOT replace the window motor, or window regulator, without making the door window adjustment first. Adjust the front side door window. Refer to <i>Front Side Door Window Adjustment</i> in SI.

### Parts Information

No parts are normally required for this repair.

<b>Version</b>	1
<b>Modified</b>	Released October 30, 2020

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION