

2021 Arteon

Engine	Part	Part Number	Quantity
2.0L Turbo: DLRB	Oil Filter	06L 115 562 B	1
	VW 504 00 Use synthetic oil SAE 0W-30	N/A	5.7L (6.0qt)
	Drain Plug Gasket	N 911 679 01	1
	Seal Ring	N 013 815 7	1
	Air Filter	5Q0 129 620 B	1

Miscellaneous	Part	Part Number	Quantity
Miscellaneous	Dust & Pollen Filter	5Q0 819 644 A	1
	Front Set Wipers	3GB 998 002	1
	Battery (Amp. Req. Vary)	000 915 105*	1

***VIN Required**

2021	Engine Code		Torque Spec
Oil drain plug Torque	2.0L	DLRB	30 Nm
Wheel hub bolt Torque	2.0L	DLRB	140 Nm

11/18/2020

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



2021 Arteon



2021 Arteon Service Reminder Reset

Resetting the service reminder display

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the service reminder can be reset as follows:

- Switch the ignition off.
- Press and hold the 0.0 button in the instrument cluster.
- Switch the ignition back on.
- Release the 0.0 button when one of the following messages appears in the instrument cluster display: **Reset oil change service?** or **Reset inspection service?**.
- Press the 0.0 button in the instrument cluster to confirm.

Do **not** reset the service interval display between service intervals; or incorrect information will be displayed.

If the oil change service was manually reset, the service interval display then also switches to a fixed service interval, even on vehicles with **flexible oil change service**.

The service message turns off after a few seconds when the engine is running or if you press the **OK/RESET** button on the windshield wiper lever or the **OK** button on the multi-function steering wheel.

If the 12 V vehicle battery in a vehicle with flexible service was disconnected for an extended period, the time for the next service cannot be calculated. Therefore, the service interval displays may show incorrect calculations. If this is the case, follow the maximum permissible maintenance intervals.

For current fluid capacity charts, please refer to the Maintenance section in Elsa.