



Ferrari North America Technical Information

Date:	November 2020
Bulletin #:	2693
Campaign #:	462
Supersedes:	
Section:	10

Models:



Subject: Replacing tool kit – Service Campaign no. 462

Please note that due to an incorrect fitting assembled on the air compressor in the tool kit, it is necessary to replace the **tool kit** included in the standard equipment on vehicles of the aforementioned model from **VIN No. 244381** to **VIN No. 255275**.

The list of vehicles for which this is necessary is given in the file attached to this Technical Information denominated “**Lista_vetture_C462_Monza SP1_SP2.pdf**”, or may be viewed directly from the **NewModis** portal with the function “**Recall and Update Campaign Management**”, entering the campaign number indicated.

To complete this campaign, the following part must be ordered from our Spare Parts Department.

- **COMPL. TOOLKIT – P/N 070006368**

Service rules

The customer may keep the original tool kit included with the vehicle by **Ferrari**.

You may recover the costs incurred for this campaign via the **Warranty System**, specifying the aforementioned part number of the kit: No labor code is envisaged for this campaign.

› Campaign number.....	462
› Cost code	23
› Malfunction code.....	7692000042
› Problem code.....	01
› Labor Code.....	76920007780
› Time.....	0.05

Thank you for your co-operation



Ferrari North America Technical Information

Date: November 2020
Bulletin #: 2693
Campaign #: 462
Supersedes:
Section: 10

Subject: Vehicles List – Service Campaign no. 462

Chassis no.

251431
253366
253364
247211
247212
247410
247409
247873
247874
248648
249278
249279
249310
250238
250855
252066
252067
252068
252989
252988
254683
254682
254686
254685
254684
254681
255275