



Technical Service Bulletin

PSS 91 HomeLink Garage Door Opener button is grayed out while driving or HomeLink GPS location pairing is not working

91 20 40 2061505/1 November 24, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad, S4, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, and S5 Sportback	2020	All	Not Applicable

Condition

Customer states:

- The HomeLink Garage Door Opener (furthermore abbreviated as UGDO) shortcut button in the MMI dropdown menu is grayed out while driving (Figure 1).
- A message "For your safety, this function is not available while driving" is displayed when "clicking" on it.




Figure 1. UGDO shortcut button grayed out.



Technical Service Bulletin

- The geolocation feature of the UGDO system is not working, despite having been stored by the customer during the pairing procedure (Figure 2).




Figure 2. UGDO geolocation pairing process.

Technical Background

A software bug in the MIB3 system causes the non-availability of the hotkey and geolocation features of the UGDO system.

Production Solution

Not applicable.

Service

1. Explain to the customer that a solution is forthcoming for the 2nd quarter of 2021, pending successful compatibility testing and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*), or through the Technical Assistance page in Elsa.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (2061505) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.