

CAMPAIGN LAUNCH STATUS

SERVICE ACTIONS – VCT SOLENOID - AJ20P 4 CYL ENGINE



CSP SERVICE ACTION N481

AFFECTED MODELS	2018-2020 MY DISCOVERY SPORT; RR EVOQUE;, RR VELAR; RANGE ROVER; RANGE ROVER SPORT. 4cyl AJ20P engines
VOLUME AFFECTED Phase 1	8,986 USA 1990 CAN
REPAIR	To prevent premature wear, a resulting MIL and a possible no start, all affected vehicles require the replacement of variable camshaft timing (VCT) solenoids on both intake an exhaust.
REPAIR TIME	Between 0.3 and 0.8 hrs based on model + drive in/out
CAMPAIGN LAUNCH	Phase 1 - Nov 3 rd 2020
Notes	Launch is staggered by VIN group over a 3-month period 44,000 units in phases 2 & 3

CSP SERVICE ACTION H299

AFFECTED MODELS	2018-2020MY F-TYPE; F-PACE; XE; XF; E-PACE 4cyl AJ20P engines
VOLUME AFFECTED Phase 1	12,221 USA 4037 CAN
REPAIR	To prevent premature wear, a resulting MIL and a possible no start, all affected vehicles require the replacement of variable camshaft timing (VCT) solenoids on both intake an exhaust.
REPAIR TIME	Between 0.2 and 0.6 hrs based on model + Drive in/out
CAMPAIGN LAUNCH	Phase 1 - Nov 3 rd 2020
Notes	Launch is staggered by VIN group over a 3-month period 25,000 units in phases 2 & 3.