

TECHNICAL TOPICS

POWERTRAIN



Fuel Gauge drops too quickly after refill

19MY – Onward RR Evoque

Customer Voice:

- The fuel gauge will drop a few miles after filling the tank.

Technical Description:

- Tolerances between the sensor mount and calibration can result in this condition.
- Only the top of the fuel level range is affected.

Status:

- Changes to the fuel tank hardware have been put into production at the supplier.
- The revisions are within the original specification of the tank, so the part number will not change.
- An SSM will be published once the new tanks are in stock in the market which will include the serial number which include the revisions.
- Current service stock tanks can be used for any other service needs.

