

TECHNICAL TOPICS

BODY/CHASSIS



Panoramic Roof Glass / Sunblind Loses One Touch Operation Function

17 – 20MY F-PACE,
18 – 20MY RR Velar

Customer Voice:

- A customer may report that the roof opening panel or the roof blind does not operate with the 'one touch' feature.

Technical Description:

- The roof opening panel or roof blind may lose 'one touch' operation due to a loss of motor synchronization.

Status:

- SSM 75106 & 75107 has been published to address this concern by providing instructions on how to initialize the roof opening panel and synchronize the motor.
- There should be no need to replace parts for this concern.
- The SSMs will be suspended once the Workshop Manual is updated with the new procedures.

