ATTENTION:						
ATTENTION: GENERAL MANAGER PARTS MANAGER	IMPORTANT - All Service Personnel Should Read and Initial in the boxes					
CLAIMS PERSONNEL	provided, right.					
SERVICE MANAGER	© 2020 Subaru of America, Inc. All rights reserved.					



SERVICE BULLETIN

APPLICABILITY: 2010-21MY Legacy / Outback

SUBJECT: Service Manual Corrections

NUMBER: 18-203-20

DATE: 11/20/20

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
	General Description	Recommended Materials	Grease	Front brake pad and support grease changed. Rear disc brake support grease added.	
2021	Legacy/	Diagnosis	Engine (H4D0YC)	Diag procedure with DTC	Diagram and diagnostic steps changed for DTCs P0480 & 0481.
2021 Cutback		Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.	
		Brakes -	Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
		General Description	Recommended Materials	Grease	Front brake pad and support grease changed. Rear disc brake support grease added.
		Engine (H4D0)	Fuel Injection	Intake Manifold	Removal steps changed, steps added.
		Transmission	CVT (TR690)	TCM Installation	Steps added to TCM installation.
		1141131111331011	CVT (TR580) TCM Installation		Steps added to TCM installation.
		Brakes	Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.
2020	Legacy/ Outback	Dianes	Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.
	ouisaon		Engine (H4DOTC)	Diagnostic procedure with DTC	Diagnostic steps changed for DTCs P0480 and 481.
		Body & Electrical/Wiring	Door Mirror	Inpection mode and diagnostics	Inspection mode and diagnostic steps added.
			Tellematics	Diagnostic procedure with DTC	Diagnostic steps changed for DTC B2A16 and U115B.
			Tire Pressure Monitor	Diagnostic procedure with DTC	Diagnostic steps changed for DTC C2921.
	System	Wiring System	CVT Control System	Electrical Diagrams changed.	
		General Description	Recommended Materials	Grease	Front brake pad and support grease changed. Rear disc brake support grease added.
			Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.
	Legacy/ Outback		Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.
			Stop Light Switch	Adjustment	Adjustment steps added.
		Diagnosis	Auto Headlight Beam Leveler System	Diagnostic procedure with DTC	Diagnostic steps changed for DTC B2910 and B2911.
			Tire Pressure Monitor	Diagnostic procedure with DTC	Diagnostic steps changed for DTC C2921.
		Body & Electrical/Wiring System	Exterior/Interior Trim	Roof Rail	Images changes and installation steps updated.

Bulletin Number: 18-203-20; Date: 11/20/20

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
		General Description	Recommended Materials	Grease	Front brake pad and support grease changed. Rear disc brake support grease added.
		Transmission	CVT (TR690)	CVT (TR690) TCM Installation	
		1141151111551011	CVT (TR580)	TCM Installation	Steps added to TCM installation.
			Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.
2018	Legacy/ Outback	Brakes	Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.
	Outback		Stop Light Switch	Adjustment	Adjustment steps added.
		Diagnosis	Auto Headlight Beam Leveler System	Diagnostic procedure with DTC	Diagnostic steps changed for DTC B2910 and B2911.
		Diagnosis	Tire Pressure Monitor	Diagnostic procedure with DTC	Diagnostic steps changed for DTC C2921.
		Body & Electrical/Wiring System	Exterior/Interior Trim	Roof Rail	Images changes and installation steps updated.
		General Description	Recommended Materials	Grease	Front brake pad and support grease changed. Rear disc brake support grease added.
		Transmission	CVT (TR690)	TCM Installation	Steps added to TCM installation.
			CVT (TR580)	TCM Installation	Steps added to TCM installation.
	Legacy/ Outback		Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.
	Outback		Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.
			Stop Light Switch	Adjustment	Adjustment steps added.
		Body & Electrical/Wiring System	Exterior/Interior Trim	Roof Rail	Images changes and installation steps updated.
		General Description	Recommended Materials	Grease	Front brake pad and support grease changed. Rear disc brake support grease added.
		T	CVT (TR690)	TCM Installation	Steps added to TCM installation.
		Transmission	CVT (TR580)	TCM Installation	Steps added to TCM installation.
	Legacy/ Outback		Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.
	JUIDAUK		Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.
			Stop Light Switch	Adjustment	Adjustment steps added.
		Body & Electrical/Wiring System	Exterior/Interior Trim	Roof Rail	Images changes and installation steps updated.

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2015 Legacy/ Outback		Transmission	CVT (TR690)	TCM Installation	Steps added to TCM installation.
		Transmission	CVT (TR580)	TCM Installation	Steps added to TCM installation.
		Brakes	Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.
			Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.
			Stop Light Switch	Adjustment	Adjustment steps added.
		Body & Electrical/Wiring System	Exterior/Interior Trim	Roof Rail	Images changes and installation steps updated.
		Diagnosis	CVT	Diagnostic procedure with DTC	Diagnostic steps changed for DTC P2762.
		Transmission	CVT	TCM Installation	Steps added to TCM installation.
2014 Legacy/ Outback			Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.
		Brakes	Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.
			Stop Light Switch	Adjustment	Adjustment steps added.
		Diagnosis	CVT	Diagnostic procedure with DTC	Diagnostic steps changed for DTC P2762.
		Transmission	CVT	TCM Installation	Steps added to TCM installation.
2013	Legacy/ Outback		Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.
			Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.
			Stop Light Switch	Adjustment	Adjustment steps added.
1 20112 1		General Description	Recommended Materials	Grease	Front brake pad and support grease changed. Rear disc brake support grease added.
		Diagnosis	CVT	Diagnostic procedure with DTC	Diagnostic steps changed for DTC P2762.
	Legacy/	Transmission	CVT	TCM Installation	Steps added to TCM installation.
	Outback	Outback Brakes	Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.
			Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.
			Stop Light Switch	Adjustment	Adjustment steps added.

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
		General Description	Recommended Materials	Grease	Front brake pad and support grease changed. Rear disc brake support grease added.
	Diagnosis	CVT	Diagnostic procedure with DTC	Diagnostic steps changed for DTC P2762.	
0011	Legacy/	Transmission	CVT	TCM Installation	Steps added to TCM installation.
2011 Cegacy/ Outback		Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.	
		Brakes	Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.
			Stop Light Switch	Adjustment	Adjustment steps added.
2010 Legacy/ Outback	General Description	Recommended Materials	Grease	Front brake pad and support grease changed. Rear disc brake support grease added.	
	Diagnosis	CVT	Diagnostic procedure with DTC	Diagnostic steps changed for DTC P2762.	
	Legacy/	Transmission	CVT	TCM Installation	Steps added to TCM installation.
	Outback	Outback Brakes	Front & rear brake pads	Installation	Grease application steps added. Grease recommendation changed.
			Front and rear disk brake assembly	Installation	Grease application steps added. Grease recommendation changed.
			Stop Light Switch	Adjustment	Adjustment steps added.

Bulletin Number: 18-203-20; Date: 11/20/20 Page 5 of 5