

2018 Plateau

LP tank is not reading

LP tank level sensor wired incorrectly

Traced sensor wires from G6 board to sensor.

Found wires connected incorrectly. Retired and tank reads correctly. Tested at board as recommended.