

Subject: Engineering Information - No Restart After Auto-Stop Event, No Crank, DTCs P0617, P26E6 P305D, U0102, U0284, U0285, U0672, U111A, U111E and/or U1348

This PI has been revised to end the need for information from the field. Please discard PIE0572.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 (New Model)	2019	2019	-	-	All	All
	Silverado 1500	2020	2020				
GMC	Sierra 1500 (New Model)	2019	2019				
	Sierra 1500	2020	2020				

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released June 22, 2020 Revised October 14, 2020 – Ended the need for further information from the field.