

Subject: Engineering Information - Loud Banging Noise Heard from Rear of Vehicle While in Motion

This PI has been revised to end the need for information from the field. Please discard PIE0573.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500/3500	2020	2020	-	-	Equipped with 6.6L Engine (RPO L5P)	Equipped with 10 SPD Transmission (RPO MGM)
GMC	Sierra 2500/3500						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released July 13, 2020 Revised October 28, 2020 – Ended the need for further information from the field.