

7-Oct-20
2020 TOFINO

The slight chirp noise that happens every 40 seconds in our 2020 Tofino is from the Atwood LPCO unit.

If it's still beeping then the CO/LP detector has to be replaced. Please provide us a physical address where to send it to.

13-Oct-20
2021 ASCENT

CUSTOMER STATES LP/CO DETECTOR CHIRPS. FOUND LP/CO DETECTOR IS IN FAULT NEEDS NEW DETECTOR.
REPLACED DETECTOR AND TESTED.

LABOR REQUESTED PLUS PART 0450053 Alarm