

Problem: Owner states – The rear awning cap is cracked, FIAMMA provided part, no charge

Cause: Mounted too tight

Repair: Rear awning cap was replaced