

SERVICE ACTION

Reference number:	SA-31-1430	Issued: 04 December, 2020
Subject:	Replace the Outboard Bonnet Vents	
Model(s):	DBX	
VIN Range:	Refer to the separately published list of affected Vehicle Identification Numbers (VINs)	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Action

Aston Martin has found that some DBX vehicles have a quality issue with bonnet outboard vent carriers installed on the bonnet. The issue is caused by high temperatures in the engine bay.

Only vehicles that have been handed over to customers or vehicles that are prepared for customer handover can be reworked.

Workshop Procedures

Do the applicable procedure for the vehicle:

- Replace the Bonnet Vents – Vehicle Set (refer to Workshop Manual Procedure 31.02.BN)
- Replace the Bonnet Vent Blades – Vehicle Set (refer to Workshop Manual Procedure 31.02.BL)

Note: *Install the old blades onto the new bonnet vents.*

Parts Data

When you order new parts, you must refer to the table below for the correct bonnet vents and bonnet vent blade options that are applicable to the vehicle.

Description	Part Number	Quantity
Right Side Bonnet Outboard Vent (vehicles with bonnet blades)	HY53-16C690-AB	1
Left Side Bonnet Outboard Vent (vehicles with bonnet blades)	HY53-16C691-AB	1
Right Side Bonnet Outboard Vent (vehicles without bonnet blades)	HY53-16C694-AB	1
Left Side Bonnet Outboard Vent (vehicles without bonnet blades)	HY53-16C695-AB	1

Warranty Data**Procedure and Labour Time**

Description	Labour Time
Remove and install the Bonnet Vents	0.45
Remove and install the Bonnet Vent Blades	0.55

If you have any questions related to this document, please refer to the 'Contact Us' link on this website or contact your local Dealer or After Sales Manager.

The English version of this document is written in Simplified Technical English to ASD-STE100™.