

**SERVICE BULLETIN**

Classification:

BT04-014c

Reference:

NTB04-053c

Date:

November 18, 2020

CUSTOMER SATISFACTION INITIATIVE**APPLIED VEHICLE:** 2004 Quest (V42)**APPLIED VINS:** 5N1BV28U*4N300000 - 345822**Service Campaign ID # B0115, B0122, and B0123 are no longer active.**

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # B0115, B0122, and B0123.
- Please discard all previous versions of NTB04-053.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
June 23, 2004	NTB04-053	Original bulletin published
October 27, 2004	NTB04-053a	Power Sliding Door Re-Initialization procedure revised
December 22, 2005	NTB04-053b	Sliding Door Squeak and Rattle Kit part number changed, and Replace and Adjust Dovetails procedure updated
November 18, 2020	NTB04-053c	Bulletin no longer active