

Technical Journal

TITLE:

Logo illumination gear shift lever

REF NO: TJ 35747.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7515		ISSUE DATE: 2020-11-05	STATUS DATE: 2020-11-13
FUNC GROUP: 4321	FUNC DESC: Gear lever carrier, complete	Page 1 of 1	

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534	ED	E400V6			E		2021-9999		-	202007-999952

CSC Customer Symptom Codes

Code	Description
27	Gear selector/Damaged knob / boot
GC	Instrument- /button lighting/Does not work

DESCRIPTION:

In cases where the illumination in the logotype on the gear shift lever is working inconsistent please follow advice under "service".

SERVICE:

Do not replace any parts.

A new CEM (Central Electronic Module) software is planned to be released year 2021 quarter 2 to solve this issue.

Warranty claim info:

No warranty claim is accepted for job described in this Technical Journal.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report Polestar" and sub concern area "Support not needed Polestar", use function group 4321.