



STAR ONLINE PUBLICATION



Case Number: S2008000187

Release Date: 11/24/2020

Symptom/Vehicle Issue: HVAC Module Sets B160F Twilight/Ambient Light Sensor Input

Discussion: Technician may find the HVAC module has set DTC B160F Twilight/Ambient Light Sensor Input. Review the vehicles built with sales codes, vehicles without (LMG) Auto Headlamps do not use a twilight sensor. The current HVAC software is looking for the twilight sensor input that is not required for this build configuration and is setting this DTC erroneously.

No further repairs should be attempted, engineering is updating the HVAC module software for a service release scheduled to be available by the 1st quarter of 2021.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found