



NUMBER: 05-003-20

GROUP: 05 - Brakes

DATE: November 3, 2020

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Brake Pedal with Booster Service

OVERVIEW:

This bulletin is informing the technician that when servicing the brake pedal or the brake booster both components need to be serviced together.

MODELS:

2019 - 2020 (DT) RAM 1500 Pickup

NOTE: This bulletin applies to vehicles within the following markets/countries: North America.

NOTE: This bulletin applies to vehicles equipped with Non-Adjustable Pedals (Sales Code XA8) or Power Adjustable Pedals (Sales Code XAP) or Power Adjustable Pedals W/Memory (Sales Code XAM).

DISCUSSION:

This bulletin is to aid the technician on awareness of that the when replacing either a brake pedal or brake booster for service that both the brake booster and brake pedal need to be replaced at the same time or component mismatch will occur.

When servicing the brake pedal or booster both components need to be serviced together for proper system function. Refer to the detailed service procedures available in DealerConnect> Service Library under: Service Info>05 per the component being serviced.

SERVICE PARTS:

NOTE: Do not order these parts unless following the service information with a customer concern.

Qty.	Part No.	Description
1(AR)	68437183AC	Fixed pedal assembly (XA8 - Sales Code)
1(AR)	68437179AC	Adjustable pedal assembly (XAP or XAM - Sales Code)
1(AR)	68518662AA	Booster - Power Brake

POLICY:

Information Only