# ATTENTION: GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER © 2020 Subaru of America, Inc. All rights reserved.



## **SERVICE BULLETIN**

APPLICABILITY: 2016-17MY Legacy and Outback NUMBER: 10-99-20

SUBJECT: HVAC Control Panel- Design Change DATE: 12/09/20

#### INTRODUCTION:

This bulletin announces availability of a new HVAC control panel in response to reports of the buttons along the lower row sticking in the "pressed" position when they are operated.



The shape of the control panel body behind the buttons was changed to prevent occurrence of this condition.

#### **PART INFORMATION:**

The part number for the new HEATER CONTROL ASSEMBLY is 72311AL11D.

**REMINDER:** Always order the most up-to-date replacement parts based on the specific VIN being repaired.

#### SERVICE PROCEDURE / INFORMATION:

**REMINDER:** Customer satisfaction and retention starts with performing quality repairs.

The service procedures for HVAC control panel replacement remain unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time, every time. This includes proper inspection criteria, necessary special tools, required processes and related one-time-use parts needed for a complete and lasting repair.

# CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

# Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Page 1 of 2

Bulletin Number: 10-99-20; Date: 12/09/20

### **WARRANTY / CLAIM INFORMATION:**

For vehicles within the Basic New Car Limited Warranty period or covered by an active Subaru Added Security Classic or Gold plan, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Labor Time	Fail Code
HVAC CONTROL PANEL R&R	A014804	0.3	YFV-81

## **IMPORTANT REMINDERS:**

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Bulletin Number: 10-99-20; Date: 12/09/20 Page 2 of 2