TECHNICAL TOPICS POWERTRAIN





Restricted Performance Message

Customer Voice:

There is a restricted performance message in the instrument pack and a Check Engine MIL.

Technical Description:

- DTC (s) are stored for the throttle.
- The metal support ring from the intake tube has become loose and restricted movement of the throttle plate.

Status:

- Should this condition be encountered, please replace the intake tube and retain both the tube and the ring for return.
- Raise an EPQR including contact information (name, email address, and phone number)

17MY – Onward Range Rover, RR Sport, Discovery, RR Velar equipped with AJ126









